









Undrained triaxial (cu) tests:
Influence of initial void ratio

Clay Hypoplasticity,
Mašín (2013)

Gertraud Medicus

CC BY